

FIG. 1




FIG. 2





FIG. 3






FIG. 5




FIG. 6A




FIG. 6B




FIG. 6C





FIG. 7






FIG. 9A




FIG. 9B





FIG. 9C



10/519762

FIG. 10

31




FIG. 11A




FIG. 11B




FIG. 11C




FIG. 12




FIG. 13A




FIG. 13B




FIG. 14




FIG. 15




FIG. 16A




FIG. 16B




FIG. 16C




FIG. 17




FIG. 18A




FIG. 18B




FIG. 18C




FIG. 18D




FIG. 19




FIG. 20




FIG. 21A




FIG. 21B




FIG. 22




FIG. 23




FIG. 24




FIG. 25





FIG. 26A  
FIG. 26B

FIG. 27





FIG. 28






FIG. 30A




FIG. 30B




FIG. 31A




FIG. 31B




FIG. 31C




FIG. 31D




FIG. 32


63

FIG. 33A




FIG. 33B




FIG. 34A




FIG. 34B




FIG. 34C




FIG. 34D




FIG. 35




FIG. 36




FIG. 37




FIG. 38




FIG. 39A


68

FIG. 39B


68

FIG. 40


68

FIG. 41A


68

FIG. 41B


68

FIG. 42


68

FIG. 43A




FIG. 43B




FIG. 44A


68

FIG. 44B


68

FIG. 45A




FIG. 45B





FIG. 46






FIG. 48




FIG. 49




FIG. 50




FIG. 51




FIG. 52




FIG. 53A  
WHEN SWITCH IS ON




FIG. 53B  
WHEN SWITCH IS OFF




FIG. 54A


101

FIG. 54B




FIG. 54C




FIG. 55A




FIG. 55B





FIG. 55C



**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER:** \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.